

EPS SSR-1c  
POWER LOSS: RPCM NIRS1 C

ACTION	EQUIP/FUNCTION LOST	CREW INDICATION	NOTES
	RPCM N1RS1C (Type V) MDM N1 2 Srv Htr	<b>Caution Messages:</b>  <b>Advisory Messages:</b>  RPCM N1RS1_C Loss of Comm - NOD1  <b>Telemetry:</b>  PCS Node1: EPS <div>NODE1:EPS</div> RPCM N1RS1 C - not Active	<div>① Since the Early Comm antennas are lost, the entire Early Comm system is lost. The internal Early Comm equipment is powered off, except for the Transceiver. The Transceiver remains powered to provide survival heater power.</div> <div>② Normally the CBMs are not powered.</div> <div>③ String B of the Node 1 and PMA 1 shell heaters are nominally primary.</div>
1 <div>PCS Node1: EPS: RPCM N1RS2 RPCM NIRS2 A</div> <div><div>•sel RPCM Detail</div><div>•sel RPC [X], [X] = <div>10</div> <div>11</div></div><div>•cmd Open <b>Execute</b></div><div>•Repeat</div></div>	1 2 CBM N1 Stbd Sec 1 (Early Comm Port Ant Pwr) CBM N1 Stbd Sec 2 (Early Comm Port Ant Htr) CBM N1 Stbd Sec 3 (Early Comm Stbd Ant Pwr) CBM N1 Stbd Sec 4 Early Comm Stbd Ant Htr)		
<b>On MCC Go</b> Perform RPCM Remove and Replace Procedure (SODF: OSO)	3 PMA1 Shell Htrs String A		